

# SAFETY ALERT

DATE: October 2020

## Operating mobile plant - Incidents and near misses

This safety alert provides safety advice for the NSW mining industry.

### Issue

Several incidents have been reported to the Resources Regulator recently where people have been exposed to significant health and safety risks due to collisions, rollovers, and interaction of mobile plant within surface operations. The severity of the outcomes of these incidents have ranged from a near miss to minor injuries of personnel involved. The potential outcome of all these incidents however could have been severe and/or fatal injuries.

### Circumstances

The Resources Regulator has identified several contributing factors in each of these incidents. As highlighted in the video (see link below), the operation of vehicles - specifically the interaction between vehicles of all size and types - is a major risk in surface mining.

**Watch video:** [Hazards in surface mining operations: Roads or other vehicle operating areas](#)



Figure 1 Light vehicle rollover on mine rehabilitation

## Recommendations

It is recommended that mine operators ensure:

- all mining areas including roadways, intersections and park up areas are designed, constructed and maintained to safely manage:
  - interactions between mobile plant and light vehicles
  - interactions between mobile plant and equipment
  - interactions between mobile plant and fixed plant and structures
  - interactions between vehicles, mobile plant and pedestrians.
- pre-use inspections are conducted on vehicles and equipment, and all defects are reported and repaired
- workers are trained and competent to operate vehicles and equipment
- vehicle and equipment operators attend work, physically and mentally capable of performing their duties (fitness for work)
- vehicles and equipment are operated within their design limits
- vehicles and equipment are operated according to the environment (drive to conditions)
- positive communication (the use of equipment numbers) is always applied when operating vehicles and equipment.



*Figure 1 Light vehicle rollover in mining area*



*Figure 2 Contact between haul truck and grader*

**NOTE:** Please ensure all relevant people in your organisation receive a copy of this safety alert and are informed of its content and recommendations. This safety alert should be processed in a systematic manner through the mine's information and communication process. It should also be placed on the mine's common area, such as your notice board where appropriate.

Visit our [website](#) to:

- find more safety alerts and bulletins
- use our searchable safety database.

© State of New South Wales through Regional NSW 2020. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (September 2020) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

## DOCUMENT CONTROL

<b>CM9 reference</b>	DOC20/784056
<b>Mine safety reference</b>	SA20-09
<b>Date published</b>	1 October 2020
<b>Authorised by</b>	Chief Inspector Office of the Chief Inspector